Maryland Historical Trust State Historic Sites Inventory Form

Stc3//7Magi No.

DOE _yes _no

575

1. Name (indicate pre	eferred name)		
historic Frame house	liy erdanarda good angga dia caverad	the freme house is a one-or	
and/or common	ineo e alivibujnos Rila e one aval de	nein tacace is dynastrically are	
2. Location	8920 Sandy Ho	10K ROAD 3K 12/1/05	
street & number north side of Sand	y Hook Road, .06 m	mile east of Clark Roachot for publication	on
city, town Sandy Hook	vicinity of	congressional district sixth	
state - Maryland	county	Washington	
3. Classification	-Militage &	the rough the main fear a face	
Category district public building(s) both site both object in process being considered X not applicable	X occupied unoccupied work in progress Accessible yes: restricted yes: unrestricted X no	Present Use agriculturemuseumcommercialparkeducational religiousentertainmentreligiousgovernmentscientificindustrialtransportatiomilitaryother:	
4. Owner of Proper		and mailing addresses of <u>all</u> owners	,
street & number		telephone no.:	
city, town		e and zip code	
5. Location of Lega	al Descripti	ion	
courthouse, registry of deeds, etc. Wash	hington County Cou	urthouse liber	
street & number Washington Stree	t	folio	
city, town Hagerstown		state Maryland	
6. Representation	in Existing	Historical Surveys	
litle			
date		federal state county	loc
depository for survey records			
city, town		state	

Condition

excellent

good

fair

___ deteriorated ___ ruins ___ unexposed

Check one unaltered X altered

Check one

___ original site
___ moved date of mo

ved date of move ____

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The frame house is a one-story structure with a gable roof main facade. The house is three-bays by three-bays and covered in a modern siding. The main facade is symmetrically arranged with a central entrance and three-section picture windows in the other bays and a single one-over-one window in the gable. There is a full-length, one-story porch on a concrete block foundation. According to the owner this structure was originally a two-story house which was reconstructed to its present shape after it was damanged in a fire. The current design of the structure is mid-20th century.

The property is located on the north side of Sandy Hook Road, approximately .06 mile east of Clark Road in Sandy Hook. The house sits back from the road. The main facade faces south.

The one-story structure is constructed of frame covered in a modern aluminum siding. The structure is built on a fieldstone foundation. The main facade is symmetrically arranged with a central entrance and a three-bay, one-story porch. On the outer bays of the first story are large three-section picture windows. In the gable is a one-over-one sash window. The porch sits on a concrete block foundation and has a stick railing, square posts, and curved brackets. The porch roof is hipped. The sides of the house have two-over-two sash windows in each bay. The gable roof has a boxed cornice and is covered in asphalt shingles. A concrete block chimney flue rises from the center of the structure.

There are no significant outbuildings on the property.

Period preh 1400 1500 1600 1700 1800 X 1900)–1499)–1599)–1699)–1799)–1899	Areas of Significance—C — archeology-prehistoric — agriculture — X architecture — art — commerce — communications	co ec ed en	mmunity nservation onomics ucation gineerin ploration dustry	y planning on g	literature military music philosophy politics/government	religion science sculpture social/ humanitarian theater transportation other (specify)
Specific	dates		Builde	r/Archi	tect		
check:	aı	icable Criteria:A nd/or icable Exception:				E F G	
		L of Significance:		80			

This site is a contributing structure in the Sandy Hook Survey District.


10.	Geographica	Data	antiapoba.			We K		
Acreage of nominated property Quadrangle name UTM References do NOT complete UTM references				Quadrangle scale				
AZone	Easting Northing	لتبا	B Zone	Eas	ting	Northing	لا	
C L L			D				LLL	
Verbal	boundary description and ju	ustification						
Liet ell	Lone Sandy Hook	ni ez skor		adar	ALE BE A P	Ale side		
	states and counties for pro			count	y boundaries	code		
List all state		perties overla	apping state or	count	y boundaries			
state		perties overla code code	epping state or county	count	y boundaries	code		
state state	states and counties for pro	perties overla code code	epping state or county	count	y boundaries	code		
state state 11.	Form Prepare	code code bd By	epping state or county	count	y boundaries April 19	code		
state state 11. name/tit	Form Prepare	code code bd By	epping state or county		April 19	code		

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.


The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust Shaw House 21 State Circle Annapolis, Maryland 21401 (301) 269-2438



WA-III-085 Frame House 18920 Sandy Hook Road (MD 180), Sandy Hook Harpers Ferry Quadrangle



1993-94 Aerial Photo



FREDERICK & COMMONWEALTH OF VIRGINIA HARPERS FERRY, VA-MD-W VA | NGTON DIVISION OF MINERAL RESOURCES QUADRANGLE JAMES L. CALVER, STATE GEOLOGIST USGS 7.5 minute map 1:24 000 1969 111-33 BISTO BALL TO



- WA-III-085
- Washington Co., Md.
- Joe Getty
- April 1983 7/82
- 5.
- Md. Hist. Trust, Annapolis, Md. South elev. (camera facing north)
- 7. 1/1